



To: MMI general managers, MMI operations team
From: John Manderfeld, president
Copies to: MMI hotel clients
Date: June 24, 2010
Subject: **URGENT: BABY CRIB RECALL**

The U.S. Consumer Product Safety Commission (CPSC), with the cooperation of seven firms, is announcing voluntary recalls of more than two million cribs to address drop-side hazards and other hazards that affect the safety of young children. The recalling firms are providing consumers with free repair kits to immobilize the drop sides or other remedies. **Do not attempt to fix these cribs with homemade remedies.**

The drop-side and fixed-side crib recalls announced today are of units manufactured between 2000 and 2009 by the companies listed below. Consumers should contact these firms directly for the appropriate remedy:

1.) Simmons drop-side cribs

Manufacturer: Simmons Juvenile Products, of New London, Wis.

Model numbers: 011641; 011671; 011941; 015341; 016061; 016771; 016821; 016831; 017201; 017211; 017351; 018500; 018501; 018502; 018510; 018511; 018512; 026261; 028061; 028081; 028180; 029061; 29062; 029071; 029180; 029561; 029562; 029571; 034060; 034560; 039180; 044091; 053091; 065071; 068261; 068271; 068561; 201060; 202060; 202080; 202180; 202181; 203060; 204060; 204180; 205060; 206060; 207060; 209560; 211060; 211080; 212060; 214060; 214080; 215060; 216060; 216070; 216080; 216180; 216180; 216570; 218060; 219560; 220180; 220181; 221060; 221070; 221070; 221077; 222060; 222070; 224060; 225060; 225070; 225080; 227560; 228060; 229060; 230060; 231070; 236180; 236187; 236188; 236189; 238060; 238069; 239180; 239187; 239189; 240060; 248069; 251060; 251069; 257060; 261060; 053091A; 251060M.

Remedy: Consumers should immediately stop using the recalled cribs and contact Simmons to request a free repair kit that will immobilize the drop side. Repair kits will be available in the next few weeks. In the meantime, find an alternate, safe sleep environment for the child, such as a bassinet, play yard or toddler bed depending on the child's age.

For more information please go to: <http://www.cpsc.gov/cpsc/pub/prerel/prhtml10/10278.html>

HOTEL LEADERSHIP

2400 Bridgeway, Suite 200, Sausalito, CA 94965-2851 • Voice: (415) 331-1061 • Fax: (415) 331-8711
E-mail: Info@HotelPros.biz • www.HotelPros.biz



2.) Million Dollar Baby Drop-Side cribs

Distributor: Bexco Enterprises, Inc., d.b.a. Million Dollar Baby of Montebello, Calif.

Drop-Side Hardware: Exposed hardware

Model Names and Numbers: Alexandria 4191, Alpha 591, Bailey 5201, Caleb 1701, Ellie 5401, Jenny Lind 371 / 391, Lauren (convertible) 4491, Lauren (pine) 5691, Lauren (w/ drawer) 4001, Lauren 4091, Naomi 4291, Oxford 2191, Pine 4-Poster 3991, Sleigh 2991, Twinkle 2301, M0391, M0591, M3691, M4191

Drop-Side Hardware: Hidden hardware

Model Names and Numbers: Anastasia M4801, Annabelle 5901 / 5941, Kendall W5921, Kirsten M5941, Leonardo 3101, Michelangelo 3401, Robin M6001, Roxanne M5921 / 5941

Remedy: Consumers should immediately stop using the recalled cribs and contact Million Dollar Baby for a free repair kit that will immobilize the drop side. In the meantime, find an alternate, safe sleeping environment for the child, such as a bassinet, play yard or toddler bed depending on the child's age. Repair kits will be available to consumers within a few weeks.

For more information please go to: <http://www.cpsc.gov/cpsc/pub/prerel/prhtml10/10277.html>

3.) Bonavita, Babi Italia and ISSI Drop-Side Cribs

Manufacturer: LaJobi Inc., of Cranbury, N.J.

Description: This recall involves all models of Bonavita, Babi Italia and ISSI drop-side cribs manufactured by LaJobi. The cribs have drop-side hardware that contains metal or plastic pegs that are recessed into either the drop side or the headboard and footboard of the crib. A label on the headboard of the crib identifies the manufacturer as LaJobi.

Remedy: Consumers should immediately stop using the recalled cribs and contact LaJobi for a free repair kit that will immobilize the drop side. In the meantime, find an alternate, safe sleep environment for the child such as a bassinet, play yard or toddler bed depending on the child's age.

For more information please go to: <http://www.cpsc.gov/cpsc/pub/prerel/prhtml10/10276.html>

4.) Jardine drop-side cribs

Manufacturer: Jardine Enterprise Ltd., of Taipei, Taiwan

Importer: Toys "R" Us, of Wayne, N.J.

Description: All Jardine drop-side cribs have been recalled. The model number and date code can be found on the labels attached to one of the end panels.



Model Numbers, Description and Date Codes: 0102B00 Natural Olympia Single 02/2007 - 11/2008, 0102P00 Black Olympia Single 04/2006 - 01/2009, 0108C00WP White Capri Single 12/2007 - 12/2008, 0108L00WP Antique Walnut Capri Single 12/2007 - 11/2008, 0108L00WP Antique Walnut Capri Single 12/2007 - 11/2008, 0115S00 Rubbed Black Claremont Single 12/2006 - 06/2007, BC-33 Dark Pine 3-1 Convertible 01/2000 - 06/2004, BC-66 White 3-1 Convertible 09/2001 - 08/2003, DA0930B Walnut Single, DA333BC Natural Madison Single 01/2004 - 11/2004, DA616BC Dark Pine Siera 2 in 1 11/2001 - 04/2004, DA616BN Natural Siera 2 in 1, DA618BC Natural Hampton 11/2002 - 06/2003, DV601BC Dark Pine Windsor Single 03/2001 - 06/2003, DV623BC Cherry Windsor Single 03/2001 - 06/2003, DV628BC White Windsor Single 02/2003 - 09/2003

Remedy: Consumers should immediately stop using the recalled cribs and contact Jardine to receive a free repair kit that will immobilize the drop side. In the meantime, find an alternate, safe sleep environment for the child, such as a bassinet, play yard or toddler bed depending on your child's age.

For more information please go to: <http://www.cpsc.gov/cpscpub/prerel/prhtml10/10275.html>

5.) Jenny Lind Cribs

Distributor: Evenflo Inc., of Miamisburg, Ohio

Description: The following Evenflo crib models are included in this recall. The model number is located on a label on the bottom beam of the headboard.

Model Names and Numbers: 012614 Evenflo Jenny Lind Crib, Maple, 0126141 Evenflo Jenny Lind Crib, Maple, 012615 Evenflo Jenny Lind Crib, White, 012616 Evenflo Jenny Lind Crib, Oak, 012617 Evenflo Jenny Lind Crib, Natural, 014614 Evenflo Jenny Lind Convertible Crib, Maple, 014615 Evenflo Jenny Lind Convertible Crib, White, 014616 Evenflo Jenny Lind Convertible Crib, Oak, 014617 Evenflo Jenny Lind Convertible Crib, Natural, 0151614 Evenflo Jenny Lind Hidden Hardware Crib, Maple, 0151615 Evenflo Jenny Lind Hidden Hardware Crib, White, 0151616 Evenflo Jenny Lind Hidden Hardware Crib, Oak, 0151617 Evenflo Jenny Lind Hidden Hardware Crib, Natural, 0161614 Evenflo Jenny Lind Hidden Hardware Crib, Maple, 0161615 Evenflo Jenny Lind Hidden Hardware Crib, White, 0161617 Evenflo Jenny Lind Hidden Hardware Crib, Natural

Remedy: Consumers should immediately stop using the recalled drop-side cribs and contact Evenflo to receive a free repair kit that will immobilize the drop side. A repair kit for the mattress support system is also available for cribs with model numbers starting with 012 and 014 that were manufactured between 2000 and 2004. In the meantime, find an alternate, safe sleep environment for the child, such as a bassinet, play yard or toddler bed depending on the child's age. The repair kits will be provided to consumers within the next several weeks.

For more information please go to: <http://www.cpsc.gov/cpscpub/prerel/prhtml10/10274.html>



6.) Delta cribs

Manufacturer: Delta Enterprise, of New York, N.Y.

Description: This recall involves Delta drop-side cribs with three different types of drop-side hardware and Delta cribs with wooden stabilizer bars that support the mattress platform. Consumers should visit www.cribrecallcenter.com for photographs and models of the affected hardware types and instructions on correct assembly of the stabilizer bars.

Drop-Side Crib Remedy: Consumers should immediately stop using the recalled drop-side cribs and contact Delta to receive a free repair kit that will immobilize the drop side. In the meantime, find an alternate, safe sleep environment for the child, such as a bassinet, play yard or toddler bed depending on the child's age.

Mattress Support Remedy: Consumers who have cribs with wooden stabilizer bars supporting the mattress should inspect the stabilizer bars to ensure they are correctly installed in accordance with the manufacturer's instructions and inspect the joints of their crib for any damage. If the stabilizer bars are installed upside down, stop using the crib immediately and contact Delta for information on how to correctly install the stabilizer bars or visit the firm's website at www.cribrecallcenter.com.

For more Information please go to:

<http://www.cpsc.gov/cpsc/pub/prerel/prhtml10/10273.html>

7.) Child Craft brand drop-side cribs

Manufacturer: Child Craft Industries, Inc. (Child Craft ceased operations in July of 2009 and sold the "Child Craft" name to Foundations Worldwide Inc., of Medina, Ohio) Foundations Worldwide, Inc. neither manufactured nor sold any of the cribs included in this recall.

Description: This recall involves drop-side Child Craft brand cribs using the style of drop-side hardware shown below. "Child Craft" appears on a label on the crib's frame and identifies the place of manufacture as Salem, Indiana or New Salisbury, Indiana.

Drop-Side Crib Name: All Child Craft Drop-Side Cribs with hardware shown on website listed below:

Model Numbers: F10151, F10171, F10181, F10281, F13311, F13761, F16001, F16011, F16131, F16661, F17001, F17701, F17731, F17801, F17811, F20161, F20181, F20191, F21041, F21081, F21091, F26131, F27301, F27771, F31061, F31701, F32901, F33301, F33601, F33801, F33901, F34101, F35101

Remedy: CPSC staff urges parents and caregivers to stop using these cribs immediately and find an alternative, safe sleeping environment for their baby. **Do not attempt to fix these cribs.** Although Foundations Worldwide did not manufacture or sell any of the recalled cribs, it has agreed to provide Child Craft owners with a rebate towards the purchase of a new, fixed-side Child Craft brand crib manufactured by Foundations Worldwide Inc.

For more Information please go to:

<http://www.cpsc.gov/cpsc/pub/prerel/prhtml10/10272.html>

HOTEL LEADERSHIP



Child Craft brand "Crib 'N' Double Bed" full size stationary-side cribs with dowel

Manufacturer: Child Craft Industries, Inc. (Child Craft ceased operations in July of 2009 and sold the "Child Craft" name to Foundations Worldwide Inc., of Medina, Ohio) Foundations Worldwide, Inc. neither manufactured nor sold any of the cribs included in this recall.

Description: All Child Craft brand cribs with the foot top dowel (as shown in the photos below) including, but not limited to, the following models: Child Craft convertible cribs F36101.

Remedy: The CPSC staff urges parents and caregivers to examine these cribs immediately and determine whether they have been assembled properly. The best way to do this is to measure the gap between the front and back sides of the crib and the dowel that runs parallel to the sides. The gap should be no more than two and three eighths inches (2-3/8"), as shown in the images below. If the gap is greater than 2 3/8", the side has been installed upside-down and needs to be re-assembled. Another indicator that the side has been installed improperly is the appearance of the barrel nut, as is visible in the image above showing an incorrect assembly. The barrel nut should be at the **bottom** of the side, not the top. If either one of these conditions is present, the side of the crib has been installed upside-down and needs to be re-assembled so that the barrel nut is not visible from the top and the gap between the dowel and the side is no greater than two and three eighths inches (2 3/8"). Consumers with these cribs should contact Foundations Worldwide, Inc., to obtain instructions and decals to affix to the stationary sides of the crib to ensure proper assembly in the future.

For more information please go to: <http://www.cpsc.gov/cpsc/pub/prerel/prhtml10/10271.html>

General managers, please check one of the following, sign and send back to the MMI office:

MMI hotel code: _____

- There are no recalled baby cribs at this hotel.
- There are recalled baby cribs at this hotel, and I have removed them from service. I will take the following corrective action:

General manager printed name

General manager signature

Date signed

Baby_Crib_Recall_2010-06-24

HOTEL LEADERSHIP

2400 Bridgeway, Suite 200, Sausalito, CA 94965-2851 • Voice: (415) 331-1061 • Fax: (415) 331-8711
E-mail: Info@HotelPros.biz • www.HotelPros.biz